ILLEGIB

VILE

CABLE SEC

TSSG/APSD

PP&B/RD

PSG/OC

REPRO AID

WEST

EAST

M&S

RRD

IEG IEG/OD SCIEN

SECUR.

SECRET CITE NPIC 7743. SAC FOR DIRI, DOSR, DISD, DM4C, DPLC; 100 SRW DAVIS MONTHAN AFE FOR SAC FOR DIRI, DUSK, DISD, DM4C, DPLC; 100 SRW DAVIS MONTHAN AFE IDO, DCOI, DCM, AEMS; 12 SAD FOR MD; DIA FOR DIAXX-1; HQ USAF FOR AFIGOS, AFXOTE; 15TH AF FOR DI, DO, DM4C.

SUBJECT: EVALUATION OF OLD MEAD MISSION 9-111

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION RANGES FROM POOR TO FAIR. THE DEGRADING FACTORS ARE VEHICLE VIBRATIONS AND A V/H FAILURE (SEE PERA 3C) WHICH RESULTED INTERPRETATION SUITABILITY RANGEST THE LACK OF SHARP EDGE DEFINITION AND CAUSED SMEARED INCLUSION OF THE THE LIGHT DIRECTION. THE INTERPRETATION SUITABILITY RANGEST AND POOR TO GOOD. CLOUD COVER AFFECTS APPROXIMATELY 22 TERROTORS.

FROM POOR TO GOOD. CLOUD COVER AFFECTS ARROXIMATELY 22 DE THE EMTITE MISSION. MISSID! DATA:

A. G-111, 4 JAMUARY 1970 S. I-9, 7711 C. A/C NO: 339

STEREO

T/O: 1310Z, C/ON: 1432Z 3404, W-23A

MY-819-1, NRTSC AVG GAMMA: 1.57 SLIT HIDTH - 3.080

3. A. EXPOSURE: ADEQUATE FOR INTERPRETATION, ALTHOUGHTLY UNDEREXPOSED IN THE EEGINNING OF THE MISSION. ALTHOUGH

T. DEMSITY AND CONTRAST: GENERALLY MEDIUM.

IEG/PHD IMAGED DEGRADATIONS: A MAJOR PORTION OF THE MISSIG MATTRIAL DISPLAYS SMEARED IMAGERY IN THE FLIGHT DIRECTION IAS DUE TO IMPROPER EMC EMICH RESULTED FROM AN ERRONEOUS WIH DIA-XX4 SIGNAL. THE VAH SIGNAL FLUCTUATED FROM 8.5 MRADS (NORMAL) SPAD TO 15 PLUS MRADS FOR THE FWD LOOKING FRAMES AND FROM 8.5 YRADS TO 11.5 MRADS FOR THE AFT LOOKING FRANES. A V-SHA DIA-AP A V-SHAPE FOR PATTERN, A FISHHOOK-SHAPED FOR PATTERN, AND A BAND OF FOR FROM THE SLIT ARE PRESENT ON THE MISSION MATERIAL. THESE LIST CMX THESE LIGHT LEAK INDUCED PATTERMS ARE DESCRIPED IN THE EVALUATION OF G-107 (NPIC 7500). SEVERAL MINUSDENSITY LINES, PARALLEL TO THE MAJORDVANCE CY AXIS, ARE PRESENT THROUGHOUT THE MISSION. HEAVY FOG PATTERNS SANITIZED ARE PRESENT ON FRAMES 462, 1092, 1130, 1146, AND 1422. THESE WITH TEXT APPEAR TO BE SLIT IMAGES AND ARE LOCATED 23 INCHES FROM THE SUPPLY END OF THE FORMAT. THE ABOVE MENTIONED FOR PATTERNS ARE SEVERE ENOUGH TO DEGRADE THE ASSOCIATED TERRAIN IMAGERY

SO THAT A SIGNIFICANT DEGRAPATION TO INTERPRETABILITY IS NOTED. D. PHYSICAL DEGRADATIONS: FINE EMULSION SCRATCHES ARE

MOTED THROUGHOUT THE MATERIAL. TWO HEAT SPLICES AND ONE ULTRA-SONIC SPLICE ARE PRESENT ON THIS MISSIOM.

E. DATA RECORDING TOUIPMENT: ALL RECORDING EQUIPMENT

FUNCTIONED PROPERLY THROUGHOUT THE MISSION.

F. OTHER: THE V/H FAILURE ALSO CAUSED AN INOREASE IN OVERLAR FROM IN PERCENT TO APPROXIMATELY 25 PERCENT. THE LAST TITLED FRAME IS 1425. THE LAST COUNTER NUMBER IS 1430. PLUC 5 PIAS WAS HELD THROUTHOUT THE MISSION. 4. POSITIVES: THE PRINTING AND RPOCESSING ARE GOOD. SECRET

END OF MESSAGE